



# End of Sale Announcement: MP70E

## OVERVIEW

<b>DATE ISSUED:</b>	Nov 1, 2018
<b>ISSUED BY:</b>	Sierra Wireless Enterprise Solutions Product Management
<b>PRODUCTS AFFECTED:</b>	MP70E Router
<b>ORDER CODES AFFECTED:</b>	MP70E Router - <b>Base</b> and <b>Wi-Fi</b> variants
<b>FOR DISTRIBUTION TO:</b>	General Distribution
<b>SUMMARY:</b>	<p>Sierra Wireless announces the last time buy and last time ship date for the MP70E Router (Base and Wi-Fi variants). This notice contains all relevant milestones and dates for the affected products.</p> <p>The AirLink® MP70 LTE-A and the latest LTE-A Pro variants remain in production. <a href="http://www.sierrawireless.com/mp70/">www.sierrawireless.com/mp70/</a></p>

## PRODUCTION MILESTONES

<b>AFFECTED MODELS:</b>	MP70E ( <b>Base</b> and <b>Wi-Fi</b> variants)
<b>LAST TIME BUY:</b>	<b>30-NOV-2018</b> The product cannot be ordered from Sierra Wireless after this date.
<b>LAST TIME SHIP:</b>	<b>30-DEC-2018</b> The last possible ship date that can be requested from Sierra Wireless.
<b>REASON:</b>	Technology obsolescence. Superseded by the FirstNet Ready™ MP70 LTE Advanced Pro.

<b>OTHER MODELS:</b>	MP70 LTE-A and MP70 LTE-A Pro ( <b>Base</b> and <b>Wi-Fi</b> variants)
<b>STATUS:</b>	Remain in production

## PRODUCT SUPPORT AND MAINTENANCE

<b>ACTIVE SOFTWARE MAINTENANCE PHASE:</b>	<b>FROM 1-NOV-2018 TO 31-MAR-2019</b> During this phase, device software will be actively maintained. Software releases will contain bug fixes and security patches only, no new features will be deployed. Following Active Software Maintenance the products move to Critical Software Maintenance (see below).
---	---



<b>CRITICAL SOFTWARE MAINTENANCE PHASE:</b>	<p><b>FROM 1-APR-2019 TO 31-DEC-2020</b> During this phase, new device software will be released if a Critical software issue or security vulnerability is discovered.</p> <p>A software issue is deemed to be Critical if it causes the Sierra Wireless product or service to become systemically unavailable or unresponsive, and there is no available resolution or workaround.</p> <p>A security vulnerability is deemed to be Critical if it scores 9 or 10 on the Common Vulnerability Scoring System Version 3.0 (CVSSv3) as determined by Sierra Wireless.</p>
<b>END OF SOFTWARE MAINTENANCE:</b>	<p><b>31-DEC-2020</b> No new device software will be released after this date.</p>

## CONTACT

<b>SALES:</b>	<p><a href="http://www.sierrawireless.com/sales">www.sierrawireless.com/sales</a></p> <p>1-877-687-7795</p>
<b>CUSTOMER SUPPORT:</b>	<p><a href="http://www.sierrawireless.com/support">www.sierrawireless.com/support</a></p>

## REVISION HISTORY

<b>NOV 1, 2018</b>	Rev1: Initial announcement
--------------------	----------------------------

## AFFECTED PART NUMBERS

PART No.	MODEL DESCRIPTION	SUGGESTED REPLACEMENT	PART No.
1103438	MP70E, US, DC	MP70 LTE-A Pro, NA, DC MP70 LTE-A, NA & EMEA, DC	1104071 1102709
1103439	MP70E, US, DC Wi-Fi	MP70 LTE-A Pro, NA, DC Wi-Fi MP70 LTE-A, NA & EMEA, DC Wi-Fi	1104073 1102743