DIGI

Product Change Notification	Date
	May 23, 2023

Product	LR54/TX54/TX64

Description of change	New firmware version 23.3.31.129 available for LR54/TX54/TX64 products. This is a major production release. Digi recommends all customers update their LR54/TX54/TX64 products to firmware v23.3.31.129

Reason for Change	New Firmware Version 23.3.31.129 provides: • Newly-designed Surelink implementation • New Features • Enhancements • Bug Fixes • Security Fixes See Release Notes for more details.

Product Notice	A new stable firmware version has been released for the Transportation cellular products, version 23.3.31.129. Use the link below to view the full list of changes, features, and fixes included in the new firmware. [LR54/TX54/TX64 Release Notes](#) **To take advantage of the new features, you must take action to update your device.** Refer to the instructions to update your firmware in the release notes above for more information. Any questions or concerns about the new firmware, or for assistance updating your device(s), please contact the Digi Support team

Affected SKUs	LR54-AA401, LR54-AW401, LR54-AA403, LR54-AW403, TX54-A106, TX54-A112, TX54-A206, TX54-A246, TX54-A146, TX64-A161, TX64-A161-PR, TX64-A121, TX64-A141, TX64-R210, TX64-R210-PR

Timing of Change	Effective Immediately

![DIGI logo]

| **Product Change Notification** | Date |
| | May 23, 2023 |

| **Product** | IX10/IX15/IX20/IX20W/IX30 |

| **Description of change** | New firmware version 23.3.31.129 available for all IX routers. This is a major production release. Digi recommends all customers update their IX products to firmware v23.3.31.129 |

| **Reason for Change** | New Firmware Version 23.3.31.129 provides:
• Newly-designed Surelink implementation
• New Features
• Enhancements
• Bug Fixes
• Security Fixes
See Release Notes for more details. |

| **Product Notice** | A new stable firmware version has been released for the IX, version 23.3.31.129. Use the link below to view the full list of changes, features, and fixes included in the new firmware.

IX Release Notes

To take advantage of the new features, you must take action to update your device. Refer to the instructions to update your firmware in the release notes above for more information.

Any questions or concerns about the new firmware, or for assistance updating your device(s), please contact the Digi Support team |

| **Affected SKUs** | IX10-00G4, IX10-00N4, IX10-00C6, IX15-00G4-XB2, IX15-00G4-XBP2, IX20-W0P4, IX20-00P4, IX20-W007, IX20-0007, IX20-W0G4, IX20-00G4, IX20-W0N4, IX20-00N4, IX20-0045, IX20-W0M1, IX20-00M1, IX30-00P7, IX30-00G4, IX30-00A4 |

| **Timing of Change** | Effective Immediately |

DIGI

| **Product Change Notification** | Date |
| | May 23, 2023 |

| **Product** | EX12/EX15/EX50 |

| **Description of change** | New firmware version 23.3.31.129 available for all Enterprise Cellular products. This is a major production release. Digi recommends all customers update their Enterprise Cellular products to firmware v23.3.31.129 |

| **Reason for Change** | New Firmware Version 23.3.31.129 provides:
• Newly-designed Surelink implementation
• New Features
• Enhancements
• Bug Fixes
• Security Fixes
See Release Notes for more details. |

| **Product Notice** | A new stable firmware version has been released for the Enterprise Cellular products, version 23.3.31.129. Use the link below to view the full list of changes, features, and fixes included in the new firmware.

Enterprise Cellular Release Notes

To take advantage of the new features, you must take action to update your device. Refer to the instructions to update your firmware in the release notes above for more information.

NOTE: 23.3.31.129 firmware is not available for 63xx-series products. 22.2.9.85 is the final major firmware release for the 63xx-series products. Patch releases for critical software bugs or security vulnerabilities will be provided as needed until 2024-03-31. The end-of-life announcement for the 63xx-series products occurred on 2022-03-31 (see PCN #220331-01)

Any questions or concerns about the new firmware, or for assistance updating your device(s), please contact the Digi Support team |

Affected SKUs	EX12-R004-OUS, EX12-0004-OUS, ASB-EX15-WXG4-GLB, ASB-EX15-XXG4-GLB, ASB-EX15-WX07-OUS, ASB-EX15-XX07-OUS, ASB-EX15-WC18-GLB, ASB-EX15-XC18-GLB, ASB-EX15-XX18-OUS-1, EX50-WXS6-GLB

Timing of Change	Effective Immediately