AirLink® ALEOS Routers

OVERVIEW

DATE ISSUED:	11-Jul-2022
ISSUED BY:	Sierra Wireless Product Management
PRODUCTS AFFECTED:	**AirLink® ALEOS Routers:** • RV55, LX60, LX40
FOR DISTRIBUTION TO:	All AirLink® ALEOS Customers
	ALEOS 4.15.4 includes a change that supports additional eSIM component suppliers and will begin to ship from Sierra's factories in AirLink ALEOS routers as additional eSIMs become available: • New AirLink routers that ship from the factory with ALEOS 4.15.4 should not be downgraded to a previous ALEOS version • If you try to downgrade an AirLink ALEOS router that uses the new eSIM components, you will see an error message and the downgrade will be prevented • Your existing routers will continue to support downgrades, even after upgrading to ALEOS 4.15.4 This is a factory only release available for RV55, LX60, LX40. The release notes will be available on The Source
	You can sign-up to the Source for product resources and subscribe to product bulletins here: https://www.sierrawireless.com/sso/signup

PRODUCT SUPPORT

WHEN IS THIS UPDATE AVAILABLE:	This update will ship from the factory as the additional components become available. This release will be available on ALMS/AM/AMM but not available to download from The Source as this is a factory only release.

CONTACT

SUPPORT:	Support https://www.sierrawireless.com/support/ The Source https://source.sierrawireless.com/

	You can sign-up to the Source for product resources and subscribe to product bulletins here: https://www.sierrawireless.com/sso/signup

REVISION HISTORY

11-Jul-2022	Initial Release