

AirLink[®] ALEOS 4.15.3 Release

OVERVIEW

DATE ISSUED:	04-Apr-2022
ISSUED BY:	Sierra Wireless Product Management
PRODUCTS AFFECTED:	AirLink® ALEOS Routers: • MP70, RV55, RV50, RV50X, LX60, LX40
FOR DISTRIBUTION TO:	All AirLink® ALEOS Customers
	 ALEOS 4.15.3 is Generally Available now. Details include: Available for MP70/MP70 Pro, RV50/RV50X/RV55/RV55 Pro, and LX40/LX60 AirLink routers Includes updated cellular radio module bootloaders to support additional cellular radio module memory components Includes support for select supply chain component substitutions Note that new AirLink routers that ship from the factory with ALEOS 4.15.2 and 4.15.3 should not be downgraded to a previous ALEOS version nor should these routers be downgraded to a previous version of radio module firmware If you attempt to downgrade an AirLink ALEOS router that cannot be downgraded, you will see an error message and the downgrade will be prevented Your existing routers will continue to support downgrades, even after upgrading ALEOS 4.15.3 Includes select bug fixes and support for component substitutions as detailed in the release notes Sierra encourages all customers to upgrade to this release ALEOS 4.15.2 release notes are available on <u>The Source</u> Note that ALEOS 4.15.2 was a factory only release: Available for MP70/MP70 Pro, RV50/RV50X/RV55/RV55 Pro ALEOS 4.15.2 release notes on <u>The Source</u>



	AirLink routers remotely. ALMS greatly simplifies managing AirLink routers, can save the cost of a truck-roll, and allows AirLink routers to remain up to date with the latest firmware and security updates.
PRODUCT SUPPORT	
WHEN IS THIS UPDATE AVAILABLE:	These updates will ship from the factory the coming weeks and will be available on ALMS/AM/AMM and <u>The Source</u> shortly.

CONTACT

SUPPORT:	Support https://www.sierrawireless.com/support/ The Source https://source.sierrawireless.com/
----------	---

REVISION HISTORY

04-Apr-2022

Initial Release